



SEILER
INSTRUMENT
& MANUFACTURING COMPANY, INC.
3433 Tree Court Industrial Blvd.
St. Louis, MO 63122 USA
800-489-2282 • 314-968-2282
Fax: 314-968-2637 Corporate
Fax: 314-968-9217 Survey
Fax: 314-968-3601 Microscope

TC030: Special Requirement Applicable to Purchase Orders for Optics

Chinese Source Prohibition

Seiler Instrument & Manufacturing Company, Inc. (SEILER) purchase orders for military optics are subject to DFAR 252.225-7007 (“PROHIBITION ON ACQUISITION OF UNITED STATES MUNITIONS LIST ITEMS FROM COMMUNIST CHINESE MILITARY COMPANIES”). Accordingly, SEILER prohibits the utilization of any optical components or raw materials glass manufactured or produced WITHIN THE PEOPLE’S REPUBLIC OF CHINA in the manufacture of any items on this purchase order. Acceptance of this purchase order constitutes certification that items delivered will NOT contain any components, raw materials, supplies, or services procured or manufactured in the People’s Republic of China.

Country of Manufacture and Export Controls

1. Unless otherwise authorized in this purchase order, all optical components shall be manufactured in the United States.
2. The technical drawings and/or specifications of the optical components ordered hereunder are EXPORT CONTROLLED and
 - a. must NOT be transmitted to any party outside of the United States, including raw material glass producers, without an export license, and
 - b. must NOT, under any circumstances, be transmitted directly or indirectly to any party in China.

Certification and Inspection Requirements

The Supplier shall provide certifications of conformance in accordance with the attached “Certification Requirements Checklist for Optical Components” with each shipment. Supplier understands that these Certifications of Conformance will be presented to the United States Government as objective evidence of Supplier’s conformance to purchase order requirements.

Record of Inspections

The Supplier must complete End Item Inspection Sheets, if provided by SEILER with the purchase order, evidencing the performance of required inspections. Non-conformances must be approved by SEILER in advance of shipment.

Inspection records shall be maintained for a minimum of five years and made available for examination during that time at no additional charge.

FAILURE TO COMPLY WITH THESE REQUIREMENTS MAY RESULT IN THE REJECTION OF THE SHIPMENT AND / OR DELAY OF PAYMENT